

BOEING

17. Seller C. Gillier SECURITY FIRE PROTECTION INCIDENT REPORT

Q	<i>[</i> 3,
The state of the s	\bigcup
U	

13:16 pm		16:01 pm		TIMI	13:16 pm	NO. OF MEN 4			REPORT NO. RO-0066			
·TE	DAY		SHIFT		PLANT	BUI	LDING	FLOOR			COLUMN	
2-20-90	<u> </u>	iesday	First		Renton	<u>L</u> _	4-63	1 1			East e	nd
ORG. NO.	ORG. N	IAME			SUPERVISOR					- 1'	HONE	
NATURE OF INCIDI	NT:	HA	ZARDOUS CON	DIT	ION: Engine 2	20 r	responded t	o buil	dir	ng 4-63	on a	
reported broken ammonia line with strong fumes in the area. On our												
arrival the north east section of the building had been evacuated												
due to the odor. The Renton Facilities Emergency Response Team was												
CAUSE OF INCIDENT: requested along with the Renton Fire Department. A private Contractor.												
Gary Belvill of Nardone Mechanical, was removing old ammonia piping												
when an accumulation of water and ammonia spilled from the pipe onto												
the floor. Approximately 3-5 gallons was spilled. An area search												
CORRECTIVE ACTION/SERVICE: by Renton Fire and Boeing ERT members was made to verify the												
evacuation. A clean up crew with protective clothing and breathing												
apparatus (level B) was sent in to clean up the spill and plug the											he	
			pe. The co	ntr	actor was sent	t to	Boeing Me	dical	for	evalu	uation	-over
TYPE OF INJURIES	SUSTAI									. 	<u> </u>	· · ·
RE LOSSES		VALUE OF	PROPERTY			PEI						•
RODUCTION MAN	HOURS					PE	R: 					
UIPMENT USED: Engine 20						EXTNG AGENT						
FIRE PERSONNEL		Lt	. D. Cook,	J.	Lipsen, W. Bou	udre	eau, M. Bar	nta				
FIRE BRIGADE PERSONNEL		1										
MUTUAL AID COS. RESPONDING		Re	nton Fire D)epa	rtment Haz-Mat	t te	e am					
EQUIPMENT		! ! 	7-2	222								
HOW WAS ALARM RECEIVED?		☐ ^{ADT}	XXX ^B C	JSINE	SS GUARD		☐ VEF	RBAL		RA	010	
DISCOVERED E	MP. NA		tt Penderga				CLOCK N		ORC	-5886	PHONI	-8122
BY		l'ia	- SAME -	151			CLOCK		ORG		231	-0122
REPORTED BY			- JAME -				O E G G K					
A.D.T. ALARM (TY					TIME			RESET				
NO. OF SPRINKLEF HEADS FUSED			<u> </u>		F RISERS		CLOSED: F	ROM			то	
FOLLOW-UP INVE	TIGAT	ION	YES	5	. 🔲 ио		FOLLOW	-UP				
RECOMMENDATIO	NS							·····························				
L												
TE 2-20-90		SIGNATURE	D. Co	104	10 00/	<i>'</i>	TITLE	ieutena	n+	! !	PHONE 237-2	2888
ADX 2660 REV. 5/74		1	<i>5</i> . CO	JUK	10.00			euceno	1116			B05-0

RO-0066 cont.

and then was released. There were no other injuries. Approximately 150 people were evacuated for 2 3/4 hours. The building was released by Safety Representitive Kevin Jacobson.

Notifications and key personnel at the scene;
Ted Frees - Maintenance (Boeing Haz-Mat Operations)
Kevin Jacobson - Safety
Chuck Hempell - Safety
Jenette Ramos - Environmental Eng.
Joyce Nelson - Chem. Lab
Yvette Barnett
Larry Weiss - Renton Fire Batt. Chief
Gary Gordon - Renton Fire Haz-Mat

Notifications;
Chief J. Johnston
Jed Selter
Chet Morris
Jim Johnson
Public Relations
Wally Alder
Human Resources